



Attorney Docket No. 122.1393

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Tadao INOUE et al.

Application No.: 09/505,783

ATTENTION

Confirmation No.: 6995

CERTIFICATE OF CORRECTION

Filed: February 17, 2000

BRANCH

U.S. Patent No.: 6,975,813

Batch No.:

Issued: December 13, 2005

For: LIGHT OUTPUT CONTROL CIRCUIT

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: May 11, 2006

By: H. J. Staas
H. J. Staas
Registration No. 22,010

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

MAY 09 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,975,813

DATED : December 13, 2005

INVENTOR(S) : Tadao INOUE et al.

In the title (54), change "DEVICE" to --CIRCUIT--.

(56) References Cited, U.S. Patent Documents, column 1, after "Yoshikawa" insert --372/29--.

(56) References Cited, U.S. Patent Documents, column 1, after "Sakurai" insert --372/29--.

(56) References Cited, U.S. Patent Documents, column 2, line 3, change "359/187" to --398/197--.

(56) References Cited, Other Publications column 2, line 4, change "couterpart" to --counterpart--.

Column 27, claim 8, line 39, change "stead-satte" to --steady-state--

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 6,975,813

No. of add'l copies
@ 50¢ per page

⇒

MAY 09 2006